



AHENSIAN PRUTEKSION LINA'LA GUÅHAN

LOURDES A. LEON GUERRERO, GOVERNOR OF GUAM • JOSHUA F. TENORIO, LIEUTENANT GOVERNOR OF GUAM  
WALTER S. LEON GUERRERO, ADMINISTRATOR

## EMAS Report Form

Report #:

EMAS FY

Date:

Inspector(s):

Complainant:

Time:

Type of Inspection:

### Existing Land Use

Land/Business Owner:

(Address/Phone)

Undeveloped  
Land

Residential

Commercial

Industrial

Location:

Inspection Findings:

Corrective Action:

Acknowledge:

Inspector's Signature:





Photograph 1. Coastline near Marbo Cave, 072921.



Photograph 2. Close-up of coastline near Marbo Cave, 072921.





Photograph 3. Abandoned Storm Drain along coast, 072921.



Photograph 4. Close-up of Abandoned Storm Drain along coast, 072921.





Photograph 5. Sedimentation with Limestone forest between Marbo Cave and fenceline, 072921.



Photograph 6. Sedimentation with Limestone forest between Marbo Cave and fenceline, 072921.





Photograph 7. Sedimentation with Limestone forest between Marbo Cave and fenceline, 072921.



Photograph 8. Sedimentation with Limestone forest between Marbo Cave and fenceline, 072921.





Photograph 9. Sedimentation with Limestone forest between Marbo Cave and fenceline, 072921.



Photograph 10. Sedimentation with Limestone forest between Marbo Cave and fenceline, 072921.





Photograph 11. Erosion along trail near fenceline, 072921.



Photograph 12. Erosion along trail near fenceline, 072921.





Photograph 13. Erosion along trail near fenceline, 072921.



Photograph 14. Erosion along trail near fenceline, 072921.





Photograph 15. Second Erosion area along fenceline, 072921.



Photograph 16. Second Erosion area along fenceline, 072921.





Photograph 17. Third Erosion area along fenceline, 072921.



Photograph 18. Third Erosion area along fenceline, 072921.





Photograph 19. Trash with limestone forest, 072921.



Photograph 20. Trash with limestone forest, 072921.